



Contents

Upgrading from older versions	2
What's New	3
General Enhancements	3
Glazing	3
Enhancement to Options	4
Arched Shapes	4
Issues Fixed	4
Windowmaker 2021 R1.1 SP1	4
Windowmaker 2021 R1.1	5



Upgrading from older versions

When upgrading please also refer to below documents for changes since your current version:

If your current version is	What's New	Release Notes
Windowmaker 2021 (v9.x)	https://windowmaker.com/en/pdf/windowmaker-2021-r9.x-release-document.pdf	
Windowmaker 2020 (v8.x)	https://windowmaker.com/en/pdf/windowmaker-2020-r8.x-release-document.pdf	
Windowmaker 2018 (v7.x)	www.windowmaker.com/EN/PDF/Windowmaker%202018%20(v7.x)%20What's%20New.pdf	www.windowmaker.com/EN/PDF/Windowmaker%202018%20(v7.x)%20Release%20Notes.pdf
Windowmaker 2012 (v6.x)	www.windowmaker.com/EN/PDF/Windowmaker%202012%20(v6.x)%20What's%20New.pdf	www.windowmaker.com/EN/PDF/Windowmaker%202012%20(v6.x)%20Release%20Notes.pdf

Windowmaker 2021 R1.1

What's New


This section lists important features/updates introduced in this release.

General Enhancements


Glazing

A new Application Setting 'Enforce security glazing in Security Area' is now available. When this is set, security glazing (Toughened/Laminated Glass) must be applied to all panes falling in the Security Area. To ensure this:


1. When the first Sales Line with Security Area applicable is created, first valid safety glazing is automatically applied.
2. When any security pane is selected on Solution page, the Glazing dialog only shows security glass.




Glazing List without Enforcement



Glazing List with Enforcement (Only security glazing is listed)



Preferences → Safety is now moved to Application Settings → Sales: Safety



	Length /	Absolute
Single Glazing	125	10
Sealed Unit	175	10

Egress Minimum Aperture	
Width	0
Height	0
Area	0
Height Range above FFL	0 - 0

Security Glass Area	
A. Above floor at Door	1500
B. To Side of Door	300
C. Above floor elsewhere	800

Enforce Safety Glazing in Security Area

Enhancement to Options

Arched Shapes

The program now does not calculate reinforcement for arched profiles.

Issues Fixed

Windowmaker 2021 R1.1 SP1

Sales - Sales line - Calculation - 10763

The program crashed if a shape condition was tested in a rule belonging to the "Flyscreen" type sub-routine. This is now corrected.

Sales - Sales line - Option - 10692

Once an answer of an Option is disallowed after creating or opening a sales line, it remained disallowed despite any change to the Sales Line and hence sometimes resulted in an error. This is now fixed.

Sales - Sales line - Safety Glazing - 10606

Sometimes error was not thrown for unsafe glazing even when a Door Pane Type was applied in a Sales Line and the "Enforce Safety Glazing" checkbox was checked in Settings. This is now corrected.

Sales - WRP Documents - 10849

Incorrect output for Page No. and "Ordered" fields is now fixed.

Manufacturing - Tracking - 10955, 10976

Problem with login to a station is now resolved. Also, issue with validating the arrival of sashes at a Station with Special handling = Frame Assembly is now resolved.

Manufacturing - Process - Cutting List - 10902

Both "Cutting List" and "Load List" reports did not get generated while "Processing" a Batch even if both were selected as required outputs on the Station. This is now resolved, and the selected reports are output correctly.

ECatalog - Part - Cost Matrix - 10866

Problem with updating any Cost Matrix which is indexed with any Option of "Optional" type is now resolved. Costs now get saved successfully.

Windowmaker 2021 R1.1

Remake Order - Status - 9031

When a Remake Order is made from a Completed Order, the default status is now Survey Completed. Earlier the program used to set the status as Ordered.

WMLite - 9276

Login issues faced by users having certain options are now resolved.

Setup - Users - 8839

Problem with selected manager not being visible on certain type of "Client" users is now resolved.

Setup - Parts - 3248

Problem with 'Type' not listing correct choices or not saving them is now corrected.

Tools - Move Options - 1872

Move Option functionality now works for Excel based systems.